


ANACONDA Copper Company

New Mexico Operations  
P.O. Box 638  
Grants, New Mexico 87020  
505/876-2211



August 15, 1980

Area Mining Supervisor  
UNITED STATES DEPARTMENT OF INTERIOR  
GEOLOGICAL SURVEY  
P.O. Box 26124  
Albuquerque, New Mexico 87125

RE: P-7/P-10 Underground Mine Report - Second Quarter, 1980

Dear Sir:

In accordance with your approval of the incorporation of the P-7 area into the P-10 underground mine, we are sending you the following data:

1. Second Quarter 1980 Resurvey, Report of Subsidence Survey, Jackpile Mine.
2. Bacterial Water Reports for the P-10 Mine Well and the New Shop Well for the Second Quarter of 1980.

Chemical and Radiological Analysis of the P-10 Mine Well and the New Shop Well for the Second Quarter of 1980.

3. Gallons of Water Pumped from the P-10 Mine Well and the New Shop Well during the Second Quarter of 1980.

Gallons of Water Discharged from the P-10 Mine during the Second Quarter of 1980.

Sincerely,

Meade A. Stirland, Manager  
Environment, Health & Safety

jls

Enclosures